

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/6/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
09:00	<ul style="list-style-type: none"> Boat safety meeting at C0.4 boat launch. Launch. MP5.5 LDB observed bank ice forming. MP5.63 LDB observed sheet ice forming. Up river of the confluence observed a crew removing the Walling Tube Sampling Devices. Up river of the confluence observed a crew removing a Walling Tube anchor. MP5.63 Railroad Trestles observed sheen collecting in the debris. Ceresco Dam observed a crew removing Walling Tube Sampling Devices. MP26.25 observed a sheen sweep boat operating in the area between MP21.5 – MP30.8. MP26.25 Spontaneous sheen observed. Quantity of sheen would not warrant a sweep boat. MP26.25 RDB observed the sheen sweep boat responding to the sheen observed. MP26.0 Observed a crew sampling CSD. MP26.0 Observed sheen around the area where the crew was sampling the CSD. Morrow Lake observed a sweep boat operating in the south cove. Morrow Lake Delta Gate C observed a crew performing curtain inspections. 		
16:00	Returned to Boat Launch E4. Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			